ECS Comiguration C					Page 10	<u> </u>	ge(s)
1. Originator	2. Log Date:	3. CCR #:		4. Rev:	5. Tel:	6. Rm #:	7. Dept.
Robert Cole	8/15/00	00-0	839	_	301-925-0799	2110C	SED
8. CCR Title: Replace 4 GB drives with 18 GB to increase AMASS cache at LaRC							
9. Originator Signature/Date				10. Class 11. Type:		12. Need Date: 8/15/00	
let P de 8/14/00				II CCR			
13. Office Manager Signature/Date					of Change: aseline Doc.	15. Priority: (If "Emergency" fill in Block 28). Routine	
16. Documentation/Drawings Impacted:         922-TDL-007, 922-TDL-042, 922-TDL-001				dule	18. CI(s) A	18. Cl(s) Affected: l0drg01, l0console1	
19. Release Affected by this Change: 20. Date due 8/16/0				• • • • • • • • • • • • • • • • • • •			
22. Source Reference: NCR (attach) Action Item Tech Ref. GSFC Other:  Procurement CCR 00-0743							
23. Problem: (use additional Sheets if necessary)  Amass cache is undersized at LaRC, console mgr. is needed for transition  24. Proposed Solution: (use additional sheets if necessary)  Replace 40x4GB disks in I0drg01 RAID with 40x18 GB to increase the size of amass cache from 127 GB to 537 GB, add new machine I0console1 - old I0icg03  25. Alternate Solution: (use additional sheets if necessary)							
26. Consequences if Change(s) are not approved: (use additional sheets if necessary)							
27. Justification for Emergency (If Block 15 is "Emergency"):							
28. Site(s) Affected: ☐EDF ☐PVC ☐VATC ☐EDC ☐ GSFC ☐LaRC ☐NSIDC ☐SMC ☐AK ☐JPL ☐EOC ☐ IDG Test Cell ☐Other functionality lab							
29. Board Comments:				30. V	Vork Assigned 1	To: 31. CCR	Closed Date:
32. EDF/SCDV CCB Chair (	Sign/Date): Di	•	pproved wd/EC <u>S</u>	App/Co	m. Disapproved	Withdraw Fv	vd/ESDIS ERB
33. M&O CCB Chair (Sign/I	Date). Di	sposition: A	wd/ECS wd/ECS	App/Co	m. Disapprove	d Withdraw Fv	/d/ESDIS ERB
34. ECS CCB Chair (Sign/D	rate): Dis	position: Ap			m. Disapprove	d Withdraw F	wd/ESDIS ERB
CM01JA00 ECS/EDF/SCDV/M&O							